

# Paslode®


## COMBI Xi





[www.spitpaslode.com](http://www.spitpaslode.com)





**NEVER STOP BUILDING**





014749



**MAG1 +**  

Ø = 2.8 - 3.1 mm  
L = 51 -> 90 mm (Smooth & Ring)  
RoundDrive® 34°

---

**MAG2 +**  

Ø = 4 mm  
L = 35 / 40 / 50 mm (Hardened Ring Nails)  
34°





= 13 000 max



		15 min.	2 500 max.
		60 min.	10 000 max.
		90 min.	13 000 max.



25%	50%	75%	100%
○	○	○	●
○	○	●	●
○	●	●	●
●	●	●	●






0 -> 300
○
○
○
●



014749



-15°C ≤ T ≤ +49°C - 1000/hour - 2 nails/second

















014749



$-15^{\circ}\text{C} \leq T \leq +49^{\circ}\text{C}$  - 1000/hour - 2 nails/second








014749



### MAG1 +







Ø = 2.8 - 3.1 mm  
L = 51 -> 90 mm (Smooth & Ring)  
RounDrive® 34°



### MAG2 +









Ø = 4 mm  
L = 35 / 40 / 50 mm (Hardened Ring Nails)  
34°









014749


















50 000



014749





## RESET



>10s

Resting position / Ruheposition / Position de repos / Ruststand /  
Posición de descanso / Posizione di riposo / Posição de descanso /  
Rozycja spoczynku / Klidová poloha / Nyugalmi állapot / ПОЛОЖЕНИЕ  
В нерабочем состоянии / Θέση αδράνειας / Hvilestilling / Viloläge  
/ Hvileposisjon / Lepoasento / Položaj mirovanja / Pokojová poloha /  
Položaj mirovanja/ وضع السكون / Ramybės padėtis / Oot easend / Miera  
stāvoklis / Hvíldarstaða



**Notes**





Route de Lyon F-26500  
Bourg-lès-Valence  
France